

FOURTH EDITION

# *Fundamentals of Heat and Mass Transfer*

---

FRANK P. INCROPERA

DAVID P. DEWITT

*School of Mechanical Engineering  
Purdue University*



JOHN WILEY & SONS

ACQUISITIONS EDITOR	Cliff Robichaud
MARKETING MANAGER	Debra Riegert
PRODUCTION MANAGER	Lucille Buonocore
SENIOR PRODUCTION EDITORS	Nancy Prinz, Tracey Kuehn
TEXT DESIGNER	*Nancy Field
COVER DESIGNER	Karin Kincheloe
MANUFACTURING MANAGER	Mark Cirillo
ILLUSTRATION EDITOR	Edward Starr

This book was set in Times Roman by General Graphic Services, and printed and bound by R.R. Donnelley, Willard. The cover was printed by Phoenix Color.

Recognizing the importance of preserving what has been written, it is a policy of John Wiley & Sons, Inc., to have books of enduring value published in the United States printed on acid-free paper, and we exert our best efforts to that end.

The paper in this book was manufactured by a mill whose forest management programs include sustained yield harvesting of its timberlands. Sustained yield harvesting principles ensure that the number of trees cut each year does not exceed the amount of new growth.

Copyright © 1981, 1985, 1990, 1996, by John Wiley & Sons, Inc.

All rights reserved. Published simultaneously in Canada.

Reproduction or translation of any part of this work beyond that permitted by Sections 107 and 108 of the 1976 United States Copyright Act without the permission of the copyright owner is unlawful. Requests for permission or further information should be addressed to the Permissions Department, John Wiley & Sons, Inc.

*Library of Congress Cataloging-in-Publication Data:*

Incropera, Frank P.  
 Fundamentals of heat and mass transfer / Frank P. Incropera, David P. DeWitt. -- 4th ed.  
 p. cm.  
 Includes index.  
 ISBN 0-471-30460-3 (cloth : alk. paper)  
 1. Heat--Transmission. 2. Mass transfer. I. DeWitt, David P., 1934-- II. Title.  
 QC320.I45. 1996  
 621.402'2--dc20 95-46179  
 CIP

Printed in the United States of America

10 9 8 7 6 5 4 3

**Case 1 Constant Surface Temperature:**  $T(0, t) = T_s$

$$\frac{T(x, t) - T_s}{T_i - T_s} = \operatorname{erf}\left(\frac{x}{2\sqrt{\alpha t}}\right) \quad (5.57)$$

$$q_s''(t) = \frac{k(T_s - T_i)}{\sqrt{\pi \alpha t}} \quad (5.58)$$

**Case 2 Constant Surface Heat Flux:**  $q_s'' = q_o''$

$$T(x, t) - T_i = \frac{2q_o''(\alpha t/\pi)^{1/2}}{k} \exp\left(\frac{-x^2}{4\alpha t}\right) - \frac{q_o'' x}{k} \operatorname{erfc}\left(\frac{x}{2\sqrt{\alpha t}}\right) \quad (5.59)$$

**Case 3 Surface Convection:**  $-k \frac{\partial T}{\partial x} \Big|_{x=0} = h[T_\infty - T(0, t)]$

$$\begin{aligned} \frac{T(x, t) - T_i}{T_\infty - T_i} &= \operatorname{erfc}\left(\frac{x}{2\sqrt{\alpha t}}\right) \\ &\quad - \left[ \exp\left(\frac{hx}{k} + \frac{h^2 \alpha t}{k^2}\right) \right] \left[ \operatorname{erfc}\left(\frac{x}{2\sqrt{\alpha t}} + \frac{h\sqrt{\alpha t}}{k}\right) \right] \end{aligned} \quad (5.60)$$

The *complementary error function*,  $\operatorname{erfc} w$ , is defined as  $\operatorname{erfc} w \equiv 1 - \operatorname{erf} w$ .

Temperature histories for the three cases are shown in Figure 5.7, and distinguishing features should be noted. With a step change in the surface temperature, case 1, temperatures within the medium monotonically approach  $T_s$  with increasing  $t$ , while the magnitude of the surface temperature gradient, and hence the surface heat flux, decreases as  $t^{-1/2}$ . In contrast, for a fixed surface heat flux (case 2), Equation 5.59 reveals that  $T(0, t) = T_s(t)$  increases monotonically as  $t^{1/2}$ . For surface convection (case 3), the surface temperature and temperatures within the medium approach the fluid temperature  $T_\infty$  with increasing time. As  $T_s$  approaches  $T_\infty$ , there is, of course, a reduction in the surface heat flux,  $q_s''(t) = h[T_s(t) - T_\infty]$ . Specific temperature histories computed from Equation 5.60 are plotted in Figure 5.8. The result corresponding to  $h = \infty$  is equivalent to that associated with a sudden change in surface temperature, case 1.




FIGURE 5.8

Temperature histories in a semi-infinite solid with sur-

# MINIMIZING RESIDUAL STRESSES IN MOLDED PARTS

by

MING JAW LIOU

B.S., Taiwan National University  
(1978)

M.S., Massachusetts Institute of Technology  
(1984)

SUBMITTED TO THE DEPARTMENT OF  
MECHANICAL ENGINEERING IN PARTIAL  
FULFILLMENT OF THE REQUIREMENTS FOR THE  
DEGREE OF

DOCTOR OF PHILOSOPHY  
IN MECHANICAL ENGINEERING

at the

MASSACHUSETTS INSTITUTE OF TECHNOLOGY


May 1987

Copyright (c) 1987 Massachusetts Institute of Technology

Signature of Author Ming Jaw Liou  
Department of Mechanical Engineering  
May 1, 1987

Certified by W. P. Suh  
Prof. Nam P. Suh  
Thesis Supervisor

Accepted by A. A. Sonin  
Prof. A. A. Sonin  
Chairman, Department Graduate Committee



### 3.2.1 Thermal Properties of the Layer

In order to raise the interface temperature between the polymer flow and the cavity surface above the glass transition temperature for a few seconds after the filling process, the thermal properties of the layer should be selected as follows.

When two semi-infinite parts with different initial temperatures  $T_1$  and  $T_2$  come into contact, the temperature  $T_0$  at the interface is governed by

$$\frac{T_1 - T_0}{T_0 - T_2} = \left( \frac{(k\rho c)_2}{(k\rho c)_1} \right)^{1/2}. \quad (3.1)$$

where

$k$  = thermal conductivity,

$\rho$  = density,

$c$  = specific heat.

The interface temperature increases with decreasing  $(k\rho c)$  of the insulation layer.  $T_0$  is not a function of time for two semi-infinite parts. The derivation of equation (3.1) is shown in Appendix B.

In situations where the plastic part and the insulation layer have finite thicknesses, Equation (3.1) is still valid as long as the outside surface temperatures of the two parts are not affected by the contact. This fact will be used as the second criterion to estimate the required thickness of the layer. From equation (3.1), the value of  $(k\rho c)$  for the insulation layer can be determined if  $T_0$  is specified, since  $T_1$ ,  $T_2$  and  $(k\rho c)$  of the polymer are known.

### 3.2.2 Thickness of the Layer

For equation (3.1) to be valid, the insulation layer should be thick enough so that the heat does not penetrate the layer within a specified time period. The

temperature history of a semi-infinite solid with step change in surface temperature from  $T_2$  to  $T_0$  is given [12] by

$$\frac{T - T_2}{T_0 - T_2} = \operatorname{erfc}\left(\frac{z}{2\sqrt{\alpha t}}\right), \quad (3.2)$$

where

$\operatorname{erfc}(u) = 1 - \operatorname{erf}(u)$  is the complementary error function,

$z \equiv$  distance from surface,

$\alpha = \frac{k}{\rho c} \equiv$  thermal diffusivity,

$t \equiv$  time.

By knowing the thermal properties of the layer from equation (3.1), the required thickness of the layer can be calculated if the time to keep the interface temperature well above  $T_g$  after filling for stress relaxation is specified.

### 3.3 Thermal Analyses

After calculating the required thermal properties and thickness of the layer based on the thermal criteria, it is necessary to check if the increase of cycle time is within the acceptable range.



It is expected that the subsequent cooling would take longer than when the insulation layer is excluded. However, the percent of increase should not be large for two reasons. First, since the thermal conductivity of polymer is much lower than those of the layer and the mold, the cooling time must be dominated by the heat conduction inside the polymer.

Second, a steep temperature gradient develops within the layer for the first few seconds while the surface temperature of the part is kept well above  $T_g$ . Although the thermal conductivity of the layer is lower than that of the mold, the

- [11] Hertzberg, R.W.  
*Deformation and Fracture Mechanics of Engineering Materials.*  
John Wiley & Sons. .
- [12] Holman, J.P.  
*Heat Transfer.*  
McGraw-Hill, Inc., 1976.
- [13] Isayev, A.I.  
Orientation Development in the Injection Molding of Amorphous Polymers.  
*Polymer Engineering and Science* 23(5):271-284, 1983.
- [14] Isayev, A.I. and Hieber, C.A.  
Toward a Viscoelastic Modelling of the Injection Molding of Polymers.  
*Rheol. Acta* 19:168-182, 1980.
- [15] John, L. I.  
Strain-Free Injection Molding.  
*Modern Plastics* 40:111, 1963.
- [16] Kamal, M. R. and Kenig, S.  
The Injection Molding of Thermoplastics, Part I: Theoretical Model.  
*Polymer Engineering and Science* 12(4):294-301, 1972.
- [17] Kim, B.H.  
*Low Thermal Inertia Injection Molding.*  
PhD thesis, Massachusetts Institute of Technology, 1983.
- [18] Kim, S.G.  
*Knowledge-Based Synthesis System for Injection Molding.*  
PhD thesis, Massachusetts Institute of Technology, 1985.
- [19] Kuo, Y. and Kamal, M.R.  
Flows of Thermoplastics in the Filling and Packing Stages of Injection Molding.  
In *Proceedings of International Conference on Polymer Processing*, MIT, Cambridge, MA., August, 1977.
- [20] Leonov, A.I., Lipkina, E.H., Paskhin, E.D. and Prokunin, A.N.  
Theoretical and Experimental Investigation of Shearing in Elastic Polymer Liquids.  
*Rheol. Acta* 15:411-426, 1976.

Complementary Error Function Table											
x	erfc(x)	x	erfc(x)	x	erfc(x)	x	erfc(x)	x	erfc(x)	x	erfc(x)
0	1.000000	0.5	0.479500	1	0.157299	1.5	0.033896	2	0.004678	2.5	0.000407
0.01	0.989717	0.51	0.470756	1.01	0.153190	1.51	0.032723	2.01	0.004475	2.51	0.000386
0.02	0.977435	0.52	0.462101	1.02	0.149162	1.52	0.031587	2.02	0.004281	2.52	0.000365
0.03	0.966159	0.53	0.453536	1.03	0.145216	1.53	0.030484	2.03	0.004094	2.53	0.000346
0.04	0.954889	0.54	0.445061	1.04	0.141350	1.54	0.029414	2.04	0.003914	2.54	0.000328
0.05	0.943628	0.55	0.436677	1.05	0.137564	1.55	0.028377	2.05	0.003742	2.55	0.000311
0.06	0.932378	0.56	0.428384	1.06	0.133856	1.56	0.027372	2.06	0.003577	2.56	0.000294
0.07	0.921142	0.57	0.420184	1.07	0.130227	1.57	0.026397	2.07	0.003418	2.57	0.000278
0.08	0.909922	0.58	0.412077	1.08	0.126674	1.58	0.025453	2.08	0.003266	2.58	0.000264
0.09	0.898719	0.59	0.404064	1.09	0.123197	1.59	0.024538	2.09	0.003120	2.59	0.000249
0.1	0.887537	0.6	0.396144	1.1	0.119795	1.6	0.023652	2.1	0.002979	2.6	0.000236
0.11	0.876377	0.61	0.388319	1.11	0.116467	1.61	0.022793	2.11	0.002845	2.61	0.000223
0.12	0.865242	0.62	0.380589	1.12	0.113212	1.62	0.021962	2.12	0.002716	2.62	0.000211
0.13	0.854133	0.63	0.372954	1.13	0.110029	1.63	0.021157	2.13	0.002593	2.63	0.000200
0.14	0.843053	0.64	0.365414	1.14	0.106918	1.64	0.020378	2.14	0.002475	2.64	0.000189
0.15	0.832004	0.65	0.357971	1.15	0.103876	1.65	0.019624	2.15	0.002361	2.65	0.000178
0.16	0.820988	0.66	0.350623	1.16	0.100904	1.66	0.018895	2.16	0.002253	2.66	0.000169
0.17	0.810008	0.67	0.343372	1.17	0.098000	1.67	0.018190	2.17	0.002149	2.67	0.000159
0.18	0.799064	0.68	0.336218	1.18	0.095163	1.68	0.017507	2.18	0.002049	2.68	0.000151
0.19	0.788160	0.69	0.329160	1.19	0.092392	1.69	0.016847	2.19	0.001954	2.69	0.000142
0.2	0.777297	0.7	0.322199	1.2	0.089686	1.7	0.016210	2.2	0.001863	2.7	0.000134
0.21	0.766478	0.71	0.315335	1.21	0.087045	1.71	0.015593	2.21	0.001776	2.71	0.000127
0.22	0.755704	0.72	0.308567	1.22	0.084466	1.72	0.014997	2.22	0.001692	2.72	0.000120
0.23	0.744977	0.73	0.301896	1.23	0.081950	1.73	0.014422	2.23	0.001612	2.73	0.000113
0.24	0.734300	0.74	0.295322	1.24	0.079495	1.74	0.013865	2.24	0.001536	2.74	0.000107
0.25	0.723674	0.75	0.288845	1.25	0.077100	1.75	0.013328	2.25	0.001463	2.75	0.000101
0.26	0.713100	0.76	0.282463	1.26	0.074764	1.76	0.012810	2.26	0.001393	2.76	0.000095
0.27	0.702582	0.77	0.276179	1.27	0.072486	1.77	0.012309	2.27	0.001326	2.77	0.000090
0.28	0.692120	0.78	0.269990	1.28	0.070266	1.78	0.011826	2.28	0.001262	2.78	0.000084
0.29	0.681717	0.79	0.263897	1.29	0.068101	1.79	0.011359	2.29	0.001201	2.79	0.000080
0.3	0.671373	0.8	0.257899	1.3	0.066092	1.8	0.010909	2.3	0.001143	2.8	0.000075
0.31	0.661092	0.81	0.251997	1.31	0.064093	1.81	0.010475	2.31	0.001088	2.81	0.000071
0.32	0.650874	0.82	0.246189	1.32	0.061935	1.82	0.010057	2.32	0.001034	2.82	0.000067
0.33	0.640721	0.83	0.240476	1.33	0.059985	1.83	0.009653	2.33	0.000984	2.83	0.000063
0.34	0.630635	0.84	0.234857	1.34	0.058086	1.84	0.009264	2.34	0.000935	2.84	0.000059
0.35	0.620616	0.85	0.229332	1.35	0.056238	1.85	0.008889	2.35	0.000889	2.85	0.000056
0.36	0.610670	0.86	0.223900	1.36	0.054439	1.86	0.008528	2.36	0.000845	2.86	0.000052
0.37	0.600794	0.87	0.218560	1.37	0.052688	1.87	0.008178	2.37	0.000803	2.87	0.000049
0.38	0.590991	0.88	0.213313	1.38	0.050984	1.88	0.007844	2.38	0.000763	2.88	0.000046
0.39	0.581261	0.89	0.208157	1.39	0.049327	1.89	0.007521	2.39	0.000725	2.89	0.000044
0.4	0.571608	0.9	0.203092	1.4	0.047715	1.9	0.007210	2.4	0.000689	2.9	0.000041
0.41	0.562031	0.91	0.198117	1.41	0.046148	1.91	0.006910	2.41	0.000654	2.91	0.000039
0.42	0.552532	0.92	0.193232	1.42	0.044624	1.92	0.006622	2.42	0.000621	2.92	0.000036
0.43	0.543113	0.93	0.188437	1.43	0.043143	1.93	0.006344	2.43	0.000589	2.93	0.000034
0.44	0.533775	0.94	0.183729	1.44	0.041703	1.94	0.006077	2.44	0.000559	2.94	0.000032
0.45	0.524518	0.95	0.179109	1.45	0.040305	1.95	0.005821	2.45	0.000531	2.95	0.000030
0.46	0.515345	0.96	0.174575	1.46	0.038946	1.96	0.005574	2.46	0.000503	2.96	0.000028
0.47	0.506255	0.97	0.170130	1.47	0.037627	1.97	0.005336	2.47	0.000477	2.97	0.000027
0.48	0.497250	0.98	0.165769	1.48	0.036346	1.98	0.005108	2.48	0.000453	2.98	0.000025
0.49	0.488332	0.99	0.161492	1.49	0.035102	1.99	0.004889	2.49	0.000429	2.99	0.000024





## GT13 - erfc Table


x	erfc x	x	erfc x	x	erfc x	x	erfc x	x	erfc x	x	erfc x
0.01	9.89E-01	0.77	2.76E-01	1.53	3.05E-02	2.29	1.20E-03	3.05	1.51E-05	3.81	7.13E-08
0.02	9.77E-01	0.78	2.70E-01	1.54	2.94E-02	2.30	1.14E-03	3.06	1.52E-05	3.82	6.59E-08
0.03	9.66E-01	0.79	2.64E-01	1.55	2.84E-02	2.31	1.09E-03	3.07	1.42E-05	3.83	6.09E-08
0.04	9.55E-01	0.80	2.58E-01	1.56	2.74E-02	2.32	1.03E-03	3.08	1.33E-05	3.84	5.63E-08
0.05	9.44E-01	0.81	2.52E-01	1.57	2.64E-02	2.33	9.84E-04	3.09	1.24E-05	3.85	5.20E-08
0.06	9.32E-01	0.82	2.46E-01	1.58	2.55E-02	2.34	9.36E-04	3.10	1.17E-05	3.86	4.80E-08
0.07	9.21E-01	0.83	2.40E-01	1.59	2.45E-02	2.35	8.89E-04	3.11	1.09E-05	3.87	4.44E-08
0.08	9.10E-01	0.84	2.35E-01	1.60	2.37E-02	2.36	8.45E-04	3.12	1.02E-05	3.88	4.09E-08
0.09	8.99E-01	0.85	2.29E-01	1.61	2.28E-02	2.37	8.03E-04	3.13	9.59E-06	3.89	3.78E-08
0.10	8.88E-01	0.86	2.24E-01	1.62	2.20E-02	2.38	7.63E-04	3.14	8.98E-06	3.90	3.49E-08
0.11	8.76E-01	0.87	2.19E-01	1.63	2.12E-02	2.39	7.25E-04	3.15	8.41E-06	3.91	3.22E-08
0.12	8.66E-01	0.88	2.13E-01	1.64	2.04E-02	2.40	6.89E-04	3.16	7.87E-06	3.92	2.97E-08
0.13	8.54E-01	0.89	2.08E-01	1.65	1.96E-02	2.41	6.54E-04	3.17	7.36E-06	3.93	2.74E-08
0.14	8.43E-01	0.90	2.03E-01	1.66	1.88E-02	2.42	6.21E-04	3.18	6.88E-06	3.94	2.52E-08
0.15	8.32E-01	0.91	1.98E-01	1.67	1.82E-02	2.43	5.89E-04	3.19	6.45E-06	3.95	2.33E-08
0.16	8.21E-01	0.92	1.93E-01	1.68	1.75E-02	2.44	5.58E-04	3.20	6.03E-06	3.96	2.15E-08
0.17	8.10E-01	0.93	1.88E-01	1.69	1.68E-02	2.45	5.31E-04	3.21	5.64E-06	3.97	1.98E-08
0.18	7.99E-01	0.94	1.84E-01	1.70	1.62E-02	2.46	5.03E-04	3.22	5.27E-06	3.98	1.82E-08
0.19	7.88E-01	0.95	1.79E-01	1.71	1.56E-02	2.47	4.78E-04	3.23	4.93E-06	3.99	1.68E-08
0.20	7.77E-01	0.96	1.75E-01	1.72	1.50E-02	2.48	4.53E-04	3.24	4.61E-06	4.00	1.55E-08
0.21	7.66E-01	0.97	1.70E-01	1.73	1.44E-02	2.49	4.29E-04	3.25	4.31E-06	4.01	1.42E-08
0.22	7.56E-01	0.98	1.66E-01	1.74	1.39E-02	2.50	4.07E-04	3.26	4.02E-06	4.02	1.31E-08
0.23	7.45E-01	0.99	1.61E-01	1.75	1.33E-02	2.51	3.86E-04	3.27	3.76E-06	4.03	1.21E-08
0.24	7.34E-01	1.00	1.57E-01	1.76	1.28E-02	2.52	3.66E-04	3.28	3.51E-06	4.04	1.11E-08
0.25	7.24E-01	1.01	1.53E-01	1.77	1.23E-02	2.53	3.46E-04	3.29	3.28E-06	4.05	1.02E-08
0.26	7.13E-01	1.02	1.49E-01	1.78	1.18E-02	2.54	3.28E-04	3.30	3.06E-06	4.06	9.40E-09
0.27	7.03E-01	1.03	1.45E-01	1.79	1.14E-02	2.55	3.11E-04	3.31	2.86E-06	4.07	8.65E-09
0.28	6.92E-01	1.04	1.41E-01	1.80	1.09E-02	2.56	2.94E-04	3.32	2.67E-06	4.08	7.95E-09
0.29	6.82E-01	1.05	1.38E-01	1.81	1.05E-02	2.57	2.79E-04	3.33	2.49E-06	4.09	7.31E-09
0.30	6.71E-01	1.06	1.34E-01	1.82	1.01E-02	2.58	2.64E-04	3.34	2.32E-06	4.10	6.72E-09
0.31	6.61E-01	1.07	1.30E-01	1.83	9.65E-03	2.59	2.50E-04	3.35	2.17E-06	4.11	6.18E-09
0.32	6.51E-01	1.08	1.27E-01	1.84	9.26E-03	2.60	2.36E-04	3.36	2.02E-06	4.12	5.68E-09
0.33	6.41E-01	1.09	1.23E-01	1.85	8.89E-03	2.61	2.23E-04	3.37	1.88E-06	4.13	5.21E-09
0.34	6.31E-01	1.10	1.20E-01	1.86	8.56E-03	2.62	2.11E-04	3.38	1.75E-06	4.14	4.79E-09
0.35	6.21E-01	1.11	1.16E-01	1.87	8.18E-03	2.63	2.00E-04	3.39	1.64E-06	4.15	4.40E-09
0.36	6.11E-01	1.12	1.13E-01	1.88	7.84E-03	2.64	1.89E-04	3.40	1.52E-06	4.16	4.04E-09
0.37	6.01E-01	1.13	1.10E-01	1.89	7.52E-03	2.65	1.79E-04	3.41	1.42E-06	4.17	3.71E-09
0.38	5.91E-01	1.14	1.07E-01	1.90	7.21E-03	2.66	1.69E-04	3.42	1.32E-06	4.18	3.40E-09
0.39	5.81E-01	1.15	1.04E-01	1.91	6.91E-03	2.67	1.59E-04	3.43	1.23E-06	4.19	3.12E-09
0.40	5.72E-01	1.16	1.01E-01	1.92	6.62E-03	2.68	1.51E-04	3.44	1.15E-06	4.20	2.87E-09
0.41	5.62E-01	1.17	9.80E-02	1.93	6.34E-03	2.69	1.42E-04	3.45	1.07E-06	4.21	2.63E-09
0.42	5.53E-01	1.18	9.50E-02	1.94	6.08E-03	2.70	1.34E-04	3.46	9.94E-07	4.22	2.41E-09
0.43	5.43E-01	1.19	9.24E-02	1.95	5.82E-03	2.71	1.27E-04	3.47	9.25E-07	4.23	2.21E-09
0.44	5.34E-01	1.20	8.97E-02	1.96	5.57E-03	2.72	1.20E-04	3.48	8.60E-07	4.24	2.03E-09
0.45	5.25E-01	1.21	8.70E-02	1.97	5.34E-03	2.73	1.13E-04	3.49	8.00E-07	4.25	1.86E-09
0.46	5.15E-01	1.22	8.45E-02	1.98	5.11E-03	2.74	1.07E-04	3.50	7.44E-07	4.26	1.70E-09
0.47	5.06E-01	1.23	8.19E-02	1.99	4.88E-03	2.75	1.01E-04	3.51	6.92E-07	4.27	1.56E-09
0.48	4.97E-01	1.24	7.95E-02	2.00	4.66E-03	2.76	9.50E-05	3.52	6.43E-07	4.28	1.43E-09
0.49	4.88E-01	1.25	7.71E-02	2.01	4.46E-03	2.77	8.96E-05	3.53	5.98E-07	4.29	1.31E-09
0.50	4.79E-01	1.26	7.48E-02	2.02	4.26E-03	2.78	8.44E-05	3.54	5.56E-07	4.30	1.20E-09
0.51	4.71E-01	1.27	7.25E-02	2.03	4.09E-03	2.79	7.98E-05	3.55	5.16E-07	4.31	1.10E-09
0.52	4.62E-01	1.28	7.03E-02	2.04	3.91E-03	2.80	7.50E-05	3.56	4.80E-07	4.32	1.00E-09
0.53	4.54E-01	1.29	6.81E-02	2.05	3.74E-03	2.81	7.07E-05	3.57	4.45E-07	4.33	9.19E-10
0.54	4.45E-01	1.30	6.60E-02	2.06	3.58E-03	2.82	6.66E-05	3.58	4.14E-07	4.34	8.41E-10
0.55	4.37E-01	1.31	6.39E-02	2.07	3.42E-03	2.83	6.28E-05	3.59	3.84E-07	4.35	7.69E-10
0.56	4.28E-01	1.32	6.19E-02	2.08	3.27E-03	2.84	5.91E-05	3.60	3.56E-07	4.36	7.03E-10
0.57	4.20E-01	1.33	6.00E-02	2.09	3.12E-03	2.85	5.57E-05	3.61	3.31E-07	4.37	6.43E-10
0.58	4.12E-01	1.34	5.81E-02	2.10	2.98E-03	2.86	5.24E-05	3.62	3.07E-07	4.38	5.88E-10
0.59	4.04E-01	1.35	5.62E-02	2.11	2.85E-03	2.87	4.94E-05	3.63	2.85E-07	4.39	5.37E-10
0.60	3.96E-01	1.36	5.44E-02	2.12	2.72E-03	2.88	4.64E-05	3.64	2.64E-07	4.40	4.91E-10
0.61	3.88E-01	1.37	5.27E-02	2.13	2.59E-03	2.89	4.37E-05	3.65	2.45E-07	4.41	4.49E-10
0.62	3.81E-01	1.38	5.10E-02	2.14	2.47E-03	2.90	4.11E-05	3.66	2.27E-07	4.42	4.10E-10
0.63	3.73E-01	1.39	4.92E-02	2.15	2.36E-03	2.91	3.87E-05	3.67	2.11E-07	4.43	3.74E-10
0.64	3.65E-01	1.40	4.77E-02	2.16	2.25E-03	2.92	3.64E-05	3.68	1.95E-07	4.44	3.43E-10
0.65	3.58E-01	1.41	4.61E-02	2.17	2.15E-03	2.93	3.42E-05	3.69	1.81E-07	4.45	3.12E-10
0.66	3.51E-01	1.42	4.46E-02	2.18	2.05E-03	2.94	3.22E-05	3.70	1.67E-07	4.46	2.85E-10
0.67	3.43E-01	1.43	4.31E-02	2.19	1.95E-03	2.95	3.02E-05	3.71	1.55E-07	4.47	2.60E-10
0.68	3.36E-01	1.44	4.17E-02	2.20	1.86E-03	2.96	2.84E-05	3.72	1.44E-07	4.48	2.37E-10
0.69	3.29E-01	1.45	4.03E-02	2.21	1.78E-03	2.97	2.67E-05	3.73	1.22E-07	4.49	2.17E-10
0.70	3.22E-01	1.46	3.89E-02	2.22	1.69E-03	2.98	2.51E-05	3.74	1.23E-07	4.50	1.98E-10
0.71	3.15E-01	1.47	3.79E-02	2.23	1.61E-03	2.99	2.35E-05	3.75	1.14E-07		
0.72	3.02E-01	1.48	3.63E-02	2.24	1.54E-03	3.00	2.21E-05	3.76	1.05E-07		
0.73	3.01E-01	1.49	3.51E-02	2.25	1.46E-03	3.01	2.08E-05	3.77	9.79E-08		
0.74	2.95E-01	1.50	3.39E-02	2.26	1.39E-03	3.02	1.95E-05	3.78	9.03E-08		
0.75	2.89E-01	1.51	3.27E-02	2.27	1.33E-03	3.03	1.83E-05	3.79	8.35E-08		

## Graphs and Tables

- GT1 - N vs p
- GT2 - 4PP Correction a
- GT3 - 4PP Correction k
- GT4 - Dry Oxidation
- GT5 - Wet Oxidation
- GT6 - Steam Oxidation
- GT7 - Oxide Color Chart
- GT8 - SiO<sub>2</sub> Equations
- GT9 - Trumbore Curves
- GT10 - Si Diffusivity Data
- GT11 - Goldsmith Curves
- GT12 - erfc Table
- GT13 -  $\alpha/\ell$  Properties
- GT14 - Ion Implant Ranges
- GT15 - BV for Diffused Junctions
- GT16 - Physical Constants
- GT17 - Vapor Pressure Curves
- GT18 - Herman Mask Set

## References

## Data sheets



Answers provided by this service may not be relevant to the materials presented in this website.

0.76	2.82E-01	1.52	3.16E-02	2.28	1.26E-03	3.04	1.72E-05	3.80	7.72E-08
------	----------	------	----------	------	----------	------	----------	------	----------

Department of Electrical and Computer Engineering  
College of Engineering - University of Illinois Urbana-Champaign

Contact ece444

Copyright © 2007 The Board of Trustees at the University of Illinois. All rights reserved.

erfc Table

x	erfc x	x	erfc x	x	erfc x	x	erfc x	x	erfc x	x	erfc x
0.01	9.89E-01	0.77	2.76E-01	1.53	3.05E-02	2.29	1.20E-03	3.05	1.61E-05	3.81	7.13E-08
0.02	9.77E-01	0.78	2.70E-01	1.54	2.94E-02	2.30	1.14E-03	3.06	1.52E-05	3.82	6.59E-08
0.03	9.66E-01	0.79	2.64E-01	1.55	2.84E-02	2.31	1.09E-03	3.07	1.42E-05	3.83	6.09E-08
0.04	9.55E-01	0.80	2.58E-01	1.56	2.74E-02	2.32	1.03E-03	3.08	1.33E-05	3.84	5.63E-08
0.05	9.44E-01	0.81	2.52E-01	1.57	2.64E-02	2.33	9.84E-04	3.09	1.24E-05	3.85	5.20E-08
0.06	9.32E-01	0.82	2.46E-01	1.58	2.55E-02	2.34	9.36E-04	3.10	1.17E-05	3.86	4.80E-08
0.07	9.21E-01	0.83	2.40E-01	1.59	2.45E-02	2.35	8.89E-04	3.11	1.09E-05	3.87	4.44E-08
0.08	9.10E-01	0.84	2.35E-01	1.60	2.37E-02	2.36	8.45E-04	3.12	1.02E-05	3.88	4.09E-08
0.09	8.99E-01	0.85	2.29E-01	1.61	2.28E-02	2.37	8.03E-04	3.13	9.59E-06	3.89	3.78E-08
0.10	8.88E-01	0.86	2.24E-01	1.62	2.20E-02	2.38	7.63E-04	3.14	8.98E-06	3.90	3.49E-08
0.11	8.76E-01	0.87	2.19E-01	1.63	2.12E-02	2.39	7.25E-04	3.15	8.41E-06	3.91	3.22E-08
0.12	8.66E-01	0.88	2.13E-01	1.64	2.04E-02	2.40	6.89E-04	3.16	7.87E-06	3.92	2.97E-08
0.13	8.54E-01	0.89	2.08E-01	1.65	1.96E-02	2.41	6.54E-04	3.17	7.36E-06	3.93	2.74E-08
0.14	8.43E-01	0.90	2.03E-01	1.66	1.89E-02	2.42	6.21E-04	3.18	6.89E-06	3.94	2.52E-08
0.15	8.32E-01	0.91	1.98E-01	1.67	1.82E-02	2.43	5.89E-04	3.19	6.45E-06	3.95	2.33E-08
0.16	8.21E-01	0.92	1.93E-01	1.68	1.75E-02	2.44	5.59E-04	3.20	6.03E-06	3.96	2.15E-08
0.17	8.10E-01	0.93	1.88E-01	1.69	1.68E-02	2.45	5.31E-04	3.21	5.64E-06	3.97	1.98E-08
0.18	7.99E-01	0.94	1.84E-01	1.70	1.62E-02	2.46	5.03E-04	3.22	5.27E-06	3.98	1.82E-08
0.19	7.88E-01	0.95	1.79E-01	1.71	1.56E-02	2.47	4.78E-04	3.23	4.93E-06	3.99	1.68E-08
0.20	7.77E-01	0.96	1.75E-01	1.72	1.50E-02	2.48	4.53E-04	3.24	4.61E-06	4.00	1.55E-08
0.21	7.66E-01	0.97	1.70E-01	1.73	1.44E-02	2.49	4.29E-04	3.25	4.31E-06	4.01	1.42E-08
0.22	7.56E-01	0.98	1.66E-01	1.74	1.39E-02	2.50	4.07E-04	3.26	4.02E-06	4.02	1.31E-08
0.23	7.45E-01	0.99	1.61E-01	1.75	1.33E-02	2.51	3.86E-04	3.27	3.76E-06	4.03	1.21E-08
0.24	7.34E-01	1.00	1.57E-01	1.76	1.28E-02	2.52	3.66E-04	3.28	3.51E-06	4.04	1.11E-08
0.25	7.24E-01	1.01	1.53E-01	1.77	1.23E-02	2.53	3.46E-04	3.29	3.28E-06	4.05	1.02E-08
0.26	7.13E-01	1.02	1.49E-01	1.78	1.18E-02	2.54	3.28E-04	3.30	3.06E-06	4.06	9.40E-09
0.27	7.03E-01	1.03	1.45E-01	1.79	1.14E-02	2.55	3.11E-04	3.31	2.86E-06	4.07	8.65E-09
0.28	6.92E-01	1.04	1.41E-01	1.80	1.09E-02	2.56	2.94E-04	3.32	2.67E-06	4.08	7.95E-09
0.29	6.82E-01	1.05	1.38E-01	1.81	1.05E-02	2.57	2.79E-04	3.33	2.49E-06	4.09	7.31E-09
0.30	6.71E-01	1.06	1.34E-01	1.82	1.01E-02	2.58	2.64E-04	3.34	2.32E-06	4.10	6.72E-09
0.31	6.61E-01	1.07	1.30E-01	1.83	9.65E-03	2.59	2.50E-04	3.35	2.17E-06	4.11	6.18E-09
0.32	6.51E-01	1.08	1.27E-01	1.84	9.26E-03	2.60	2.36E-04	3.36	2.02E-06	4.12	5.68E-09
0.33	6.41E-01	1.09	1.23E-01	1.85	8.89E-03	2.61	2.23E-04	3.37	1.88E-06	4.13	5.21E-09
0.34	6.31E-01	1.10	1.20E-01	1.86	8.56E-03	2.62	2.11E-04	3.38	1.75E-06	4.14	4.79E-09
0.35	6.21E-01	1.11	1.16E-01	1.87	8.18E-03	2.63	2.00E-04	3.39	1.64E-06	4.15	4.40E-09
0.36	6.11E-01	1.12	1.13E-01	1.88	7.84E-03	2.64	1.89E-04	3.40	1.52E-06	4.16	4.04E-09
0.37	6.01E-01	1.13	1.10E-01	1.89	7.52E-03	2.65	1.79E-04	3.41	1.42E-06	4.17	3.71E-09
0.38	5.91E-01	1.14	1.07E-01	1.90	7.21E-03	2.66	1.69E-04	3.42	1.32E-06	4.18	3.40E-09
0.39	5.81E-01	1.15	1.04E-01	1.91	6.91E-03	2.67	1.59E-04	3.43	1.23E-06	4.19	3.12E-09
0.40	5.72E-01	1.16	1.01E-01	1.92	6.62E-03	2.68	1.51E-04	3.44	1.15E-06	4.20	2.87E-09
0.41	5.62E-01	1.17	9.80E-02	1.93	6.34E-03	2.69	1.42E-04	3.45	1.07E-06	4.21	2.63E-09
0.42	5.53E-01	1.18	9.50E-02	1.94	6.08E-03	2.70	1.34E-04	3.46	9.94E-07	4.22	2.41E-09
0.43	5.43E-01	1.19	9.24E-02	1.95	5.82E-03	2.71	1.27E-04	3.47	9.25E-07	4.23	2.21E-09
0.44	5.34E-01	1.20	8.97E-02	1.96	5.57E-03	2.72	1.20E-04	3.48	8.60E-07	4.24	2.03E-09
0.45	5.25E-01	1.21	8.70E-02	1.97	5.34E-03	2.73	1.13E-04	3.49	8.00E-07	4.25	1.86E-09
0.46	5.15E-01	1.22	8.45E-02	1.98	5.11E-03	2.74	1.07E-04	3.50	7.44E-07	4.26	1.70E-09
0.47	5.06E-01	1.23	8.19E-02	1.99	4.89E-03	2.75	1.01E-04	3.51	6.92E-07	4.27	1.56E-09
0.48	4.97E-01	1.24	7.95E-02	2.00	4.88E-03	2.76	9.50E-05	3.52	6.43E-07	4.28	1.43E-09
0.49	4.88E-01	1.25	7.71E-02	2.01	4.48E-03	2.77	8.96E-05	3.53	5.98E-07	4.29	1.31E-09
0.50	4.79E-01	1.26	7.48E-02	2.02	4.28E-03	2.78	8.44E-05	3.54	5.56E-07	4.30	1.20E-09
0.51	4.71E-01	1.27	7.25E-02	2.03	4.09E-03	2.79	7.96E-05	3.55	5.16E-07	4.31	1.10E-09
0.52	4.62E-01	1.28	7.03E-02	2.04	3.91E-03	2.80	7.50E-05	3.56	4.80E-07	4.32	1.00E-09
0.53	4.54E-01	1.29	6.81E-02	2.05	3.74E-03	2.81	7.07E-05	3.57	4.45E-07	4.33	9.19E-10
0.54	4.45E-01	1.30	6.60E-02	2.06	3.58E-03	2.82	6.66E-05	3.58	4.14E-07	4.34	8.41E-10
0.55	4.37E-01	1.31	6.39E-02	2.07	3.42E-03	2.83	6.28E-05	3.59	3.84E-07	4.35	7.69E-10
0.56	4.28E-01	1.32	6.19E-02	2.08	3.27E-03	2.84	5.91E-05	3.60	3.56E-07	4.36	7.03E-10
0.57	4.20E-01	1.33	6.00E-02	2.09	3.12E-03	2.85	5.57E-05	3.61	3.31E-07	4.37	6.43E-10
0.58	4.12E-01	1.34	5.81E-02	2.10	2.98E-03	2.86	5.24E-05	3.62	3.07E-07	4.38	5.88E-10
0.59	4.04E-01	1.35	5.62E-02	2.11	2.85E-03	2.87	4.94E-05	3.63	2.85E-07	4.39	5.37E-10
0.60	3.96E-01	1.36	5.44E-02	2.12	2.72E-03	2.88	4.64E-05	3.64	2.64E-07	4.40	4.91E-10
0.61	3.88E-01	1.37	5.27E-02	2.13	2.59E-03	2.89	4.37E-05	3.65	2.45E-07	4.41	4.49E-10
0.62	3.81E-01	1.38	5.10E-02	2.14	2.47E-03	2.90	4.11E-05	3.66	2.27E-07	4.42	4.10E-10
0.63	3.73E-01	1.39	4.92E-02	2.15	2.36E-03	2.91	3.87E-05	3.67	2.11E-07	4.43	3.74E-10
0.64	3.65E-01	1.40	4.77E-02	2.16	2.25E-03	2.92	3.64E-05	3.68	1.95E-07	4.44	3.43E-10
0.65	3.58E-01	1.41	4.61E-02	2.17	2.15E-03	2.93	3.42E-05	3.69	1.81E-07	4.45	3.12E-10

0.66	3.51E-01	1.42	4.46E-02	2.18	2.05E-03	2.94	3.22E-05	3.70	1.67E-07	4.46	2.85E-10
0.67	3.43E-01	1.43	4.31E-02	2.19	1.95E-03	2.95	3.02E-05	3.71	1.55E-07	4.47	2.60E-10
0.68	3.36E-01	1.44	4.17E-02	2.20	1.86E-03	2.96	2.84E-05	3.72	1.44E-07	4.48	2.37E-10
0.69	3.29E-01	1.45	4.03E-02	2.21	1.78E-03	2.97	2.67E-05	3.73	1.22E-07	4.49	2.17E-10
0.70	3.22E-01	1.46	3.89E-02	2.22	1.69E-03	2.98	2.51E-05	3.74	1.23E-07	4.50	1.98E-10
0.71	3.15E-01	1.47	3.76E-02	2.23	1.61E-03	2.99	2.35E-05	3.75	1.14E-07		
0.72	3.02E-01	1.48	3.63E-02	2.24	1.54E-03	3.00	2.21E-05	3.76	1.05E-07		
0.73	3.01E-01	1.49	3.51E-02	2.25	1.46E-03	3.01	2.08E-05	3.77	9.76E-08		
0.74	2.95E-01	1.50	3.39E-02	2.26	1.39E-03	3.02	1.95E-05	3.78	9.03E-08		
0.75	2.89E-01	1.51	3.27E-02	2.27	1.33E-03	3.03	1.83E-05	3.79	8.35E-08		
0.76	2.82E-01	1.52	3.16E-02	2.28	1.26E-03	3.04	1.72E-05	3.80	7.72E-08		